

How Quick-Release Fasteners Are Manufactured: Process & QC

Engineering Hardware & Fasteners · engineeringhardware.com/how-quick-release-fasteners-are-manufactured-process-qc

July 21, 2026 · Nigen

Key Takeaways

104 - Clamping Handle Screw (Medium) — DIN 6336 □ GN 313 (Series 043)

104 - Clamping Handle Screw (Medium) — DIN 6336

□ GN 313 (Series 043) — DIN 6336 □ GN 313

- Quick-release fasteners enable tool-free panel access via mechanisms like quarter-turn, ball-lock, and cam-lever actions.
- Material options include stainless steel, alloy steel, and brass, with finishes such as zinc plating and passivation.
- Selecting the correct grip range and actuation type is critical for ensuring reliable, long-lasting joints.

- Quick-release fasteners are widely applied in aerospace, automotive, and industrial equipment where rapid maintenance is required.

Overview of the Quick-Release Fastener Production Process

108 - All-Metal Prevailing Torque Hex Lock Nut (Type 1) — GB/T 6184 — ISO
108 - All-Metal Prevailing Torque Hex Lock Nut (Type 1) —
GB/T 6184 — ISO 7042 (Series 047) — GB/T 6184 — ISO
7042

When sourcing quick-release fasteners for demanding industrial applications, procurement teams need confidence that every component will perform reliably under repeated, high-frequency use. Achieving this consistency starts with a tightly controlled manufacturing process that transforms raw materials into precision-engineered assemblies. Quick-release fasteners—encompassing quarter-turn studs, ball-lock pins, and cam-lock receptacles—require multi-stage production sequences that integrate cold forming, machining, heat treatment, and surface finishing. Understanding these stages helps buyers assess a supplier’s capability to deliver parts that meet exact dimensional,

mechanical, and durability specifications.



(https://www.youtube.com/watch?v=_uL6xCv4Lrc)

(https://www.youtube.com/watch?v=_uL6xCv4Lrc)

► Watch video: https://www.youtube.com/watch?v=_uL6xCv4Lrc (https://www.youtube.com/watch?v=_uL6xCv4Lrc)

Quick accurate positioner Fasteners | SpanClamps — by SpanClamps | Reduce Changeover Time on YouTube

Quick accurate positioner #Fasteners <https://www.spanclamps.com/quarter-turn-accurate-positioner> Quick accurate positioneru00a00...

Materials and Inputs Used

The foundation of any high-quality quick-release fastener is the raw material. Steel wire rod grades dominate production, with carbon steels (e.g., C1010-C1022, 10B21) offering an optimal balance of formability and strength for studs and receptacles. For higher load requirements or demanding environmental conditions, alloy steels such as 4140 and 4340 are selected after careful review of the application's tensile and fatigue needs. Stainless steel grades (304, 316) are specified when corrosion resistance is critical, while brass may be used in electrical or non-magnetic applications. Springs and retaining elements typically utilize drawn spring steel wire or strip conforming to ASTM A313 or equivalent standards. All incoming material is verified against material test certificates to confirm chemical composition, grain structure, and mechanical properties before production begins.

Step-by-Step Manufacturing Stages

Production starts with **wire drawing** for components that originate from coil stock. The wire rod is drawn through a series of dies to achieve precise diameters and improve surface finish. For stud-type quick-release fasteners, the drawn wire then moves to **cold heading** or progressive **cold forming**. Multi-station headers upset the wire to create the head profile, undercuts, and, where required, a reduced-diameter shank in one continuous operation—minimizing material waste and preserving grain flow. Parts that feature more complex geometries, such as cam lobes or retention grooves, may start from bar stock and undergo CNC turning or milling after initial forming.

When the design includes a threaded section (common on quick-release bolt fasteners), the blank passes to **thread rolling**. Flat-die or planetary rolling machines displace material to form threads without cutting, which increases thread strength and fatigue resistance. Following thread rolling, **heat treatment** is applied to achieve the specified hardness and toughness. The parts are austenitized, quenched in oil or polymer, and tempered in continuous belt furnaces to relieve internal stresses and refine the microstructure. For stainless steel components, solution annealing

and rapid cooling may be employed instead.

The final manufacturing stage is **surface treatment**. Carbon and alloy steel fasteners typically receive zinc plating (clear or trivalent passivation), zinc-nickel alloy plating, or black oxide to prevent corrosion. Stainless steel parts may be passivated to enhance their natural oxide layer. If a specific color or dry lubricant is required, organic top-coats or PTFE-based coatings can be applied. After surface finishing, the individual pieces are ready for assembly—pressing balls into housings, inserting springs, and snapping on retaining rings using automated or semi-automated assembly workstations.

Equipment and Techniques That Drive Quality

The precision of quick-release fasteners depends on the capability of the production equipment. Modern multi-station headers with up to five or six dies can form intricate shapes at speeds exceeding 100 parts per minute while holding diameter tolerances within ± 0.03 mm. Thread rolling machines equipped with servo-driven dies ensure consistent thread pitch and form. Heat treatment is performed in mesh-belt furnaces with controlled atmosphere and

precise temperature profiling to avoid decarburization and ensure uniform hardness. For surface treatment, automated barrel plating lines with programmable rectifiers and chemical analysis systems deliver consistent coating thicknesses across high-volume runs. Optical coordinate measuring machines (CMMs) and laser micrometers provide rapid, non-contact dimensional verification at multiple process stages.

In-Line Quality Checkpoints During Production

Quality assurance is embedded throughout the manufacturing sequence, not just at final inspection. Drawn wire is checked for diameter and surface defects using eddy current testers. After cold heading, samples from each production lot are measured for critical dimensions—head height, shank diameter, under-head fillet radius—with optical comparators. Hardness testing (Rockwell or Vickers) is performed after heat treatment on every batch to ensure conformance to the specified range, typically 32–42 HRC for studs or per customer print. Threads are checked with go/no-go gauges and, in high-reliability applications, with 3D thread scanners that verify full profile and pitch diameter. After plating, coating

thickness is verified using X-ray fluorescence (XRF) or magnetic induction methods, and adhesion is tested via tape or bend tests. Finally, assembled fasteners undergo functional cycling tests to confirm smooth operation and correct locking force.

Capacity, Consistency, and Scalability for Bulk Orders

A well-structured quick-release fastener manufacturing line can deliver annual volumes in the millions of pieces while maintaining Cp and Cpk process capability indices above 1.33. Suppliers that invest in multi-spindle cold formers, in-house die-making shops, and automated assembly cells can scale output rapidly without compromising quality. Statistical process control (SPC) software monitors critical characteristics in real time, flagging any drift before non-conforming parts are produced. For large blanket orders, safety stock programs of raw material and semi-finished blanks are often maintained to absorb demand spikes and reduce lead times. This combination of robust processes and scalability gives bulk buyers reliable, repeatable sourcing for global supply chains.

Request a Factory or Process Overview

To evaluate how a manufacturer's production system aligns with your quick-release fastener requirements, request a detailed process overview or schedule a virtual factory tour. An experienced engineering team can walk you through material traceability, process control plans, and inspection reports, giving you the transparency needed to make an informed sourcing decision.

Quick-Release Fastener Types and Operating Mechanisms

Quick-release fasteners are components that secure panels, covers, and structural elements while allowing rapid access without tools. The most common designs fall into four categories: quarter-turn fasteners, ball-lock pins, toggle clamps, and cam-action bolt fasteners. Each type suits specific access frequency, load, and safety requirements in industrial equipment, aerospace, and automotive systems.

Quarter-Turn and Cam-Lock Fasteners

Quarter-turn fasteners, often called turnlocks, use a stud and receptacle that engage with a 90° rotation. Brands like Camloc and Dzus are widely specified in aerospace and motorsport. The stud typically features a cross-pin that locks under a spring-loaded receptacle, providing vibration resistance. Materials range from passivated stainless steel to zinc-plated alloy steel, with optional waterproofing seals.

Ball-Lock and Push-Button Pins

Ball-lock pins release by depressing a button that retracts balls at the pin tip, enabling instant insertion or removal through aligned holes. These are common in machine guarding, scaffolding, and adjustable fixtures. Detent pins, a variant, rely on spring-loaded balls and require a pull force instead of button activation. Standard diameters follow metric and imperial increments, and pins are often manufactured from hardened alloy steel with a black oxide or electroless nickel finish for corrosion resistance.

Quick-Release Bolt Fasteners

Quick-release bolt fasteners combine a cam lever with a threaded or bayonet stud to replace standard hex bolts in high-frequency access panels. The lever's eccentric cam pulls the joint tight when closed, and the fastener loosens when the lever is opened. These bolts are typically machined from heat-treated alloy steel or stainless steel, with load ratings comparable to similar-sized **Hex Bolts — ISO 4014 / ISO 4017**

(<https://engineeringhardware.com/fastener/hex-bolts/>). They are used on machinery enclosures, mold doors, and vibration-prone assemblies where tool-free operation reduces changeover time.

Key Facts for Industrial Buyers

- Actuation types: quarter-turn, push-button, cam-lever, spring-loaded detent.
- Common materials: stainless steel A2/A4, heat-treated alloy steel, brass.
- Surface finishes: zinc plating (clear or yellow), black oxide, electroless nickel, passivation.
- Environmental options: IP-rated seals, corrosion-resistant coatings for marine or chemical exposure.

- Load capacity depends on fastener design, material grade, and mounting substrate; consult manufacturer's data sheets.
- Typical application industries: aerospace access panels, automotive hoods and spoilers, industrial machine guarding, electronic enclosures.

Selection Criteria for Procurement Professionals

When sourcing quick-release fasteners for production or MRO, evaluate these factors:

- **Actuation force and cycle life:** Specified as the number of operations without failure; critical for high-duty-cycle assembly lines.
- **Grip range and panel thickness:** Fasteners are designed for specific total material thickness; ordering the correct grip length prevents premature wear.
- **Retention type:** Some fasteners are captive, others are lose when unlocked—choose based on safety and ease of use.
- **Tooling and installation:** Many quick-release fasteners require special punch-and-die tooling for panel holes; confirm lead times for tooling with the manufacturer.

- **Regulatory compliance:** Aerospace applications may require NASM or MIL-spec certifications; industrial applications may cite ISO 898-1 for property classes of mating bolts.

Request a Quote for Your Quick-Release Fastener Requirements

To evaluate specific types, materials, and installation parameters, send your specifications, including drawings or panel thickness data. Our engineering team will provide a detailed recommendation and quotation covering MOQ, lead time, and certification options for your target volume.

Frequently Asked Questions

What are the main types of quick release fasteners?—

The main types include quarter-turn fasteners (turnlocks), ball-lock and push-button pins, toggle clamps, and cam-action bolt fasteners. Each type uses a distinct mechanism—rotation, button actuation, lever clamping, or cam leverage—to allow tool-free assembly and disassembly.

How does a quarter-turn fastener work? -

A quarter-turn fastener uses a stud with a cross-pin that engages a spring-loaded receptacle when rotated 90 degrees. The spring tension holds the stud locked under vibration, and a simple quarter-turn releases it, often via a screwdriver slot or wing head.

What materials are used for quick release fasteners in industrial applications? -

Common materials include stainless steel (grades A2 and A4) for corrosion resistance, heat-treated alloy steel for strength, and brass for non-magnetic or decorative needs. Finishes like zinc plating, black oxide, electroless nickel, and passivation add environmental durability.

Where are quick release bolt fasteners commonly used? -

Quick release bolt fasteners replace standard **hex bolts** (<https://engineeringhardware.com/fastener/hex-bolts-grade-c/>) in machinery enclosures, mold doors, and vibration-prone assemblies where frequent access is required. They are common in industrial

automation, packaging equipment, and automotive service panels.

How do I choose the correct grip length for a quarter-turn fastener?—

Grip length must match the total thickness of the panels being joined, including any gaskets. Manufacturers provide grip range charts; selecting the correct range ensures the stud engages fully without bottoming out, maintaining proper clamping force and cycle life.
